Certificate of Inspection

PARAMOUNT FIRE ARMOUR LTD

The Coach House, 50 Marsh Lane, King's Lynn, Norfolk, PE30 3AE Tel: 01553 679001

Email: info@paramountfirearmour.co.uk

34164

Date: 20 September 2021

Expiry Date: end September 2022

We hereby certify, as the competent persons carrying out the servicing of the fire equipment at the location/s stated below, portable Fire Fighting equipment will be installed and / or maintained in accordance to BS5306. Fire Alarm systems will be installed and / or maintained in accordance to BS5839. Emergency Lighting maintained in accordance to BS5266. (Customer must retain this copy. Replacements will be chargeable)

Customer Name & Address:	Location:
Matthew Reed. (47LR)	HMO Property:
HMO Property:	47 Loke Road
47 Loke Road	King's Lynn
King's Lynn	Norfolk.
Norfolk.	PE30 2AZ
PE30 2AZ	UK
UK	

Quantity	Equipment Serviced
•	British Standard part 6 type detection system at this location, all detection tested on this service visit:
4.0000	Smoke Detector/s; Mains connected with battery backup and integral sounder. Activated on test:
	4 x good.
	Interconnected to other fire alarm devices within this building?
	YES.
	These devices are only in common areas.
1.0000	Heat Detectors; Mains connected with battery backup and integral sounder.
	Activated on test:
	1 x good.
	Interconnected to other fire alarm devices within this building?
	YES.
	Located in Kitchen.
1.0000	ALL devices on Fire Alarm system at this location.

0.0000	Annual Fire Extinguisher inspection:
	Quantities serviced & condition, as noted below:
3.0000	Service - Foam, AFFF Fire Extinguisher/s:
	3 x good.
1.0000	Visual inspection completed:
	Fire Blanket/s:
	1 x good.

0.0000	We can verify that on this day, all above only, are now in good operational order and in their correct location.
	Unless otherwise stated with names of whom attended, training has not been given on this day.
1.0000	**PLEASE NOTE**
	ALL Fire Extinguisher spares where required are inclusive of this overall charge, opposed to a lesser initial
	fee, then the extras The only additions would be hydraulic test exchange or replacement equipment. Both of
	which will not, or would not have been supplied without your prior consent.
0.0000	*************
0.0000	Fire Risk Assessment needs to consider:
	The implications of having no detection within the bedrooms at this location.

Instruction on the use of fire extinguishers given to:

Fire awareness and evacuation procedures discussed

It has been noted on this day that portable Fire Extinguishers are merely a first aid measure in fighting fire.

Equipment discharged/discussed at time of instruction Water Foam CO2 Dry Powder Fire Blanket

Guidance to Clients: Ref: BS 5306: Part 3 1985, Para 7: Monthly Inspection

It is recommended that regular inspection of all extinguishers, spare gas cartridges and replacement charges should be carried out by a responsible person at intervals, at least monthly, to make sure that appliances are in their proper position and have not been discharged or lost pressure (in the case of fire extinguishers fitted with a pressure indicator), or suffered obvious damage.

Service Engineer: R. Palmer Date: 20 September 2021

Customer Signature: Print Name:

(Customer must retain this copy. Replacements will be chargeable)