Certificate of Inspection

PARAMOUNT FIRE ARMOUR LTD

The Coach House, 50 Marsh Lane, King's Lynn, Norfolk, PE30 3AE Tel: 01553 679001 Email: info@paramountfirearmour.co.uk

35376

Date: 22 June 2022 **Expiry Date:** Call out: Fire Alarm activation.

We hereby certify, as the competent persons carrying out the servicing of the fire equipment at the location/s stated below, portable Fire Fighting equipment will be installed and / or maintained in accordance to BS5306. Fire Alarm systems will be installed and / or maintained in accordance to BS5266. (Customer must retain this copy. Replacements will be chargeable)

Customer Name & Address:	Location:
My House Online. (47QA)	HMO Property:
HMO Property:	47 Queens Avenue
47 Queens Avenue	King's Lynn
King's Lynn	Norfolk.
Norfolk.	PE30 5LR
PE30 5LR	UK
UK	

Quantity	Equipment Serviced
1.0000	Call Out: 06:37hrs
	Completed 09:32hrs same day.
	Appears to have been a genuine false alarm caused by an older smoke detector in Zone, Detector in question was located in the back ground floor Bedroom. Device replaced and tested on this day, system reset and in good order. See image attachments.

Instruction on the use of fire extinguishers given to: Fire awareness and evacuation procedures discussed It has been noted on this day that portable Fire Extinguishers are merely a first aid measure in fighting fire. Equipment discharged/discussed at time of instruction Water Foam CO2 **Dry Powder Fire Blanket** Guidance to Clients: Ref: BS 5306: Part 3 1985, Para 7: Monthly Inspection It is recommended that regular inspection of all extinguishers, spare gas cartridges and replacement charges should be carried out by a responsible person at intervals, at least monthly, to make sure that appliances are in their proper position and have not been discharged or lost pressure (in the case of fire extinguishers fitted with a pressure indicator), or suffered obvious damage. Service Engineer: R. Palmer Date: 22 June 2022 **Customer Signature: Print Name:** (Customer must retain this copy. Replacements will be chargeable)