

Certificate of Inspection

PARAMOUNT FIRE ARMOUR LTD

The Coach House, 50 Marsh Lane, King's
Lynn, Norfolk, PE30 3AE
Tel: 01553 679001
Email: info@paramountfirearmour.co.uk

34311

Date: 21 October 2021

Expiry Date: end March 2022

We hereby certify, as the competent persons carrying out the servicing of the fire equipment at the location/s stated below, portable Fire Fighting equipment will be installed and / or maintained in accordance to BS5306. Fire Alarm systems will be installed and / or maintained in accordance to BS5839. Emergency Lighting maintained in accordance to BS5266.
(Customer must retain this copy. Replacements will be chargeable)

Customer Name & Address:	Location:
My House Online. (47QA) HMO Property: 47 Queens Avenue King's Lynn Norfolk. PE30 5LR UK	HMO Property: 47 Queens Avenue King's Lynn Norfolk. PE30 5LR UK

Quantity	Equipment Serviced
1.0000	<i>ALL COMMON AREAS DETECTION ON FIRE ALARM SYSTEM TESTED ON THIS INTERIM SIX MONTHLY SERVICE VISIT.</i>
1.0000	<i>Fire Alarm Panel, conventional Premier SX 2Z/2S-in use. charging battery backup at: 26.9vdc Screw to front of panel found to be missing. 1 x sounder fuse cradle on Sounder2 not seating correctly. Although tampered with, the panel currently registers no faults and is in good order. Screw in panel replaced.</i>
2.0000	<i>Main Panel battery backup, 2 x 3.2's new in March 2021. Reading on test: 13.49v / 3.56ah 12.96v / 3.69ah</i>
3.0000	<i>Manual Call Points: 3 x good.</i>
2.0000	<i>Smoke Detectors: 2 x good.</i>
2.0000	<i>Heat Detector: 2 x good.</i>
0.0000	<i>Sounders on Fire Alarm System, activated in good order on pre-warned tests.</i>

Instruction on the use of fire extinguishers given to:

Fire awareness and evacuation procedures discussed

It has been noted on this day that portable Fire Extinguishers are merely a first aid measure in fighting fire.

Equipment discharged/discussed at time of instruction Water Foam CO2 Dry Powder Fire Blanket

Guidance to Clients: Ref: BS 5306: Part 3 1985, Para 7: Monthly Inspection

It is recommended that regular inspection of all extinguishers, spare gas cartridges and replacement charges should be carried out by a responsible person at intervals, at least monthly, to make sure that appliances are in their proper position and have not been discharged or lost pressure (in the case of fire extinguishers fitted with a pressure indicator), or suffered obvious damage.

Service Engineer: R. Palmer



Date: 21 October 2021

Customer Signature:

Print Name:

(Customer must retain this copy. Replacements will be chargeable)