

# **DOMESTIC ELECTRICAL INSTALLATION CONDITION REPORT**

This report is not valid if the serial

number has been defaced or altered

### Small installations up to 100 A single phase supply

25549646

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

PART 1 : DETAILS OF THE CONTRACTOR, CLIENT AND INSTALL	ATION	
DETAILS OF THE CONTRACTOR Registration No:	DETAILS OF THE CLIENT Contractor Reference Number (CRN): N/A Name: My House online Address: My House Online, 4 Riserside Business Centre, Crossbank Road, King's Lynn, Norfolk	Address: 47 Loke Road, King's Lynn, Norfolk
Postcode: PE32 1XA Tel No: 01485601241	Postcode: PE30 2HD Tel No: N/A	Postcode: PE30 2AZ Tel No: N/A
PART 2 : PURPOSE OF THE REPORT		
Purpose for which this report is required: Expired Previous Report.		
Date(s) when inspection and testing was carried out: (29/06/2022	) Records available: (	available: (
PART 3 : SUMMARY OF THE CONDITION OF THE INSTALLATIO	N	
General condition of the installation (in terms of electrical safety): satisfactory		
Estimated age of electrical installation: ( N/A ) years Evidence of	additions or alterations: () Overall assessment of the ir	nstallation is: Satisfactory* (delete as appropriate)
PART 4 : DECLARATION		
INSPECTION AND TESTING I, being the person responsible for the inspection and testing of the electrical i existing installation, hereby CERTIFY that the information in this report, includin stated extent of the installation and the limitations on the inspection and testing. Name (capitals): REVIEWED BY QUALIFIED SUPERVISOR Name (capitals): JASON TODD	g the observations (page 2) and the attached schedules, provides an accurate a	
*An unsatisfactory assessment indicates that dangerous (CODE C1) and/or notentially dang	aerous (CODE C2) conditions have been identified in PART 6, or that Further Investigation	(CODE FI) without delay is required

 This report is based on the model forms shown in Appendix 6 of BS 7671

 Published by Certsure LLP
 Certsure LLP operates the NICEIC & ELECSA brands

 Warwick House, Houghton Hall Park, Houghton Regis, Dunstable, LU5 5ZX

DPN18C



### This report is not valid if the serial number has been defaced or altered 25549646

;

# **DOMESTIC ELECTRICAL INSTALLATION CONDITION REPORT**

### Small installations up to 100 A single phase supply

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

PART 5: NEXT INSPECTION		
I/We (as indicated on page 1) recommend that subject to the necessary remedial work being taken, this installation should be further inspected and tested after an interval of not more than 5	years/XXXXX	\$* (delete as appropriate)
Give reason for recommendation: As per regulation recommendations.	<u></u>	
PART 6: OBSERVATIONS AND RECOMMENDATIONS FOR ACTIONS TO BE TAKEN		
CODES:       One of the following Codes, as appropriate, has been allocated to each of the observations made below to indicate to the person(s) responsible for the electrical installation the degree of urgency for remedial action       CODE C1 'Danger Present'       CODE C2 'Potentially Dangerous'       CODE C3 'Improvement Recommended'	'Furth	CODE FI er Investigation Required'
Referring to the Schedule of Items Inspected (see PART 10), the attached Schedule of Circuit Details and Test Results (see PART 12), and subject to any agreed limitations listed in PART 7:		
There are no items adversely affecting electrical safety (), OR The following observations and recommendations for action are made:		
Item No Observation(s)	Code C3	Location Reference
() (	() (C3	()
(2) ( outside light requires suitable external cable )) (3) ( socket in kitchen has a fine crack on the front	(C3)	()
	()	()
	()	()
	()	()
	()	()
	()	()
	()	()
() () ()	()	()
	()	()
	()	()
() ()	()	( )
	()	( )
()	()	( )
	()	( )
	()	()
	()	()
Additional pages? ( <u>None</u> ) State page numbers: ( <u>N/A</u> )	,	,
Immediate action required for items: ( <u>N/A</u> ) Improvement recommended for items: ( <u>1,2,3</u> )		)
Urgent remedial action required for items: (N/A) Further investigation required for items: (N/A)		)

\*The proposed date for the next inspection should take into consideration any legislative or licensing requirements and the frequency and quality of maintenance that the installation can reasonably be expected to receive during its intended life. The period should be agreed between relevant parties.

DPN18C



#### **DPN18C** number has been defaced or altered **DOMESTIC ELECTRICAL INSTALLATION CONDITION REPORT**

This report is not valid if the serial

### Small installations up to 100 A single phase supply

25549646

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

PART 7 : DETAILS AND LIMITATIONS O	N THE INSPECTION AND TESTING					
the building or underground, have not been visuall	y inspected unless specifically agreed between the	es concealed within trunking and conduits, or cables Client and the Inspector prior to inspection.				hin the fabric of
Agreed limitations including the reasons, if any		n wiring and junction boxes installed into the				
Extent of sampling (inspection only) : 1no acce Operational limitations including the reasons:	essory from each circuit in every room. No insulation resistance test between Live a	and Neutral as unable to disconnect loads.	Α	greed with (print name): N/A	(see additional (see additional	page No. <mark>N/A</mark> ) page No. <mark>N/A</mark> )
PART 8 : SUPPLY CHARACTERISTICS	AND EARTHING ARRANGEMENTS					
System type and earthing arrangements         TN-C-S: ( N/A)         TN-S: ( N/A)         Other (state): N/A         Supply protective device         (BS (EN))         Type: ()	TT: () AC Other (state): Confirmation	ype of live conductors 1-phase, 2-wire: ( Y ) N/A of supply polarity: of supply ( <i>as detailed on attached schedule)</i> Pag	(•	Nature of supply parameters Nominal line voltage to Earth, <i>U</i> Nominal frequency, <i>f</i> : Prospective fault current, <i>I<sub>pf</sub></i> <sup>(1)'</sup> External loop impedance, <i>Z<sub>e</sub></i> <sup>(1)*</sup>	( <sup>50</sup> ) Hz *: ( <sup>0.05</sup> ) kA	<sup>(1)</sup> By enquiry, measurement, or by calculation
PART 9 : PARTICULARS OF INSTALLA	TION REFERRED TO IN THIS REPORT					
Means of Earthing         Distributor's facility:       (	Main protective conductors         Earthing conductor:         (material Copper         csa 16         Connection / continuity verified:         (M/A)         Main protective bonding conductors:         (material Copper         csa 10         csa 10         csa 10         csa 10         csa 10         connection / continuity verified:	Main protective bonding connections         Water installation pipes:       ()         Gas installation pipes:       ()         Structural steel:       (N/A)         Oil installation pipes:       (.N/A)         Lightning protection:       (N/A)         Other (state):       N/A	Type: Location: No. of poles: Current rating: Where an RCD RCD rated resi	(1.00) A is used as the main switch dual operating current, $I_{\Delta n}$ :	)	) (N/A) A (240) ∨ (N/A) mA (N/A) ms

\*Where the installation is supplied by more than one source, the higher or highest values of prospective fault current, I of, and external earth fault loop impedance, Z<sub>e</sub>, must be recorded.

All fields must be completed. Enter either, as appropriate: '\screwt' if Acceptable condition; 'N/A' if Not applicable; 'LIM' if a Limitation exists;

or Code appropriately - CODE 'C1', 'C2', 'C3' or 'FI' (codes to be recorded in PART 6, with additional comments (where appropriate) on attached numbered sheets)



## number has been defaced or altered **DOMESTIC ELECTRICAL INSTALLATION CONDITION REPORT**

This report is not valid if the serial

### Small installations up to 100 A single phase supply

25549646

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

#### **PART 10 : SCHEDULE OF ITEMS INSPECTED**

	ternal condition of intake equipment (visual inspection only)		4. Co	onsumer unit(s) / Distribution board(s)		4.15	Protection against electromagnetic effects where cables	
	inadequacies are identified with the intake equipment, it is recom e person ordering the report informs the appropriate authority)	mended	4.1	Adequacy of working space / accessibility to			enter metallic consumer unit / enclosure:	()
	Service cable:	()		consumer unit / distribution board:	()		RCDs provided for fault protection – includes RCBOs:	(N/A)
		( <b>v</b> )		Security of fixing:	()		RCDs provided for additional protection – includes RCBOs:	() ,N/A
	Service head:		I		()	4.18	Confirmation of indication that SPD is functional:	()
	Earthing arrangement:	()	4.4	Condition of enclosure(s) in terms of fire rating:	()	4.19	Adequacy of AFDD(s), where specified:	(N/A)
1.4	Meter tails:		4.5	Enclosure not damaged / deteriorated so as to impair safety:	()	4.20	Confirmation that conductor connections, including	
	a) Cutout fuse to meter	()	4.6	Presence of linked main switch:	()		connections to busbars, are correctly located in terminals	
	b) Meter to consumer unit	()	4.7	Operation of main switch(es) (functional check):	()		and are tight and secure:	()
1.5	Metering equipment:	()	4.8	Main switch capable of being secured in the OFF position:	()	5. Di	stribution / final circuits	
1.6	Isolator (where present):	( <u>N/A</u> )	4.9	Operation of circuit-breakers and RCDs to prove		5.1	Identification of conductors:	()
2. Pr	esence of adequate arrangements for other sources			disconnection (functional check):	()	5.2	Cables correctly supported throughout:	()
21	Adequate arrangements where a generating set operates		4.10	Correct identification of circuits and protective devices:	()	5.3	Condition of insulation of live parts:	()
	as a switched alternative to the public supply:	(N/A	4.11	Presence of appropriate circuit charts, warning and other notic	ces:	5.4	Non-sheathed live conductors protected by enclosure in condu	uit,
2.2	Adequate arrangements where generating set operates in parallel with the public supply:	(N/A)		a) Provision of circuit charts/schedules or equivalent forms of information	()		ducting or trunking (including confirmation of the integrity of conduit and trunking systems):	(••••••)
	Presence of alternative / additional supply warning notices:	(N/A)		b) Warning notice of method of isolation where live parts not capable of being isolated by a single device	()	5.5	Adequacy of cables for current-carrying capacity with regard to the type and nature of installation:	(•
3. Ea	rthing and bonding arrangements				· • ·	5.6	Adequacy of protective devices; type and rated current for	· • .
3.1	Presence and condition of distributor's earthing arrangement:	()		c) Periodic inspection and testing notice	() ( <b>V</b> )		fault protection:	()
3.2	Presence and condition of earth electrode connection,	,		d) Presence of RCD six-monthly notice, where required	()	5.7	Presence and adequacy of circuit protective conductors:	()
	where appropriate:	()		e) Warning notice of non-standard (mixed) colours		5.8	Co-ordination between conductors and overload	(
3.3	Confirmation of adequate earthing conductor size:	()		of conductors present	()		protection devices:	()
3.4	Accessibility and condition of earthing conductor at	· • .		f) All other required labelling provided	()	5.9	Wiring system(s) appropriate for the type and nature of the installation and external influences:	()
	Main Earthing Terminal (MET):	()	4.12	Compatibility of protective device(s), base(s) and other		Б 10	Cables adequately protected against mechanical damage	()
	Confirmation of adequate main protective bonding conductor sizes:	()		components; correct type and rating (no signs of	()	5.10	and abrasion:	()
3.6	Accessibility and condition of main protective bonding	(		unacceptable thermal damage, arcing or overheating):	()	5 11	Provision of additional protection by 30 mA RCD (see Note):	(,
	conductor connections:	()	4.13	Single-pole switching or protective devices in the line conductors only:	(	0.11	a) For all socket-outlets with a rated current not exceeding 32 A	(N/A
	Accessibility and condition of other protective		1 1 1	Protection against mechanical damage where cables			<ul> <li>b) For mobile equipment not exceeding a rating of 32 A</li> </ul>	
3.8	bonding connections: Provision of earthing and bonding labels at all	()	4.14	enter consumer unit / distribution board:	()		for use outdoors	(N/A ()
	appropriate locations:	()					<li>c) For cables concealed in walls / partitions at a depth of less than 50 mm</li>	()

**DPN18C** 

**All fields must be completed.** Enter either, as appropriate: '\scripts' if Acceptable condition;

'N/A' if Not applicable;

'LIM' if a Limitation exists:



### This report is not valid if the serial number has been defaced or altered 25549646

DPN18C

# DOMESTIC ELECTRICAL INSTALLATION CONDITION REPORT

Small installations up to 100 A single phase supply

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

#### PART 10 : SCHEDULE OF ITEMS INSPECTED

<ul> <li>d) For cables concealed in walls / partitions containing metal parts regardless of depth</li> <li>e) For all AC final circuits supplying luminaires</li> </ul>	<ul> <li>b) Acceptable location (local / remote) ()</li> <li>c) Clearly identified by position and / or durable marking(s) ()</li> <li>6.3 For isolation only:</li> </ul>	8.2       Where used as a protective measure, requirements for SELV or PELV are met:         8.3       Shaver sockets comply with BS EN 61558-2-5 (formerly BS 3535): (N/A)
Note: Older installations designed prior to BS 7671: 2008 may not have been provided with RCDs for additional protection.	a) Warning label(s) posted in situations where live parts cannot be isolated by the operation of a single device ()	<ul> <li>8.4 Presence of supplementary bonding conductors unless not required by BS 7671: 2018. (</li></ul>
5.12 Provision of fire barriers, sealing arrangements and protection against thermal effects:       ()         5.13 Band II cables segregated / separated from Band I cables:       (N/A)         5.14 Cables segregated / separated from communications cabling:       (N/A)	7. Current-using equipment (permanently connected)         7.1 Condition of equipment in terms of IP rating:         7.2 Equipment does not constitute a fire hazard:         7.3 Enclosure not damaged / deteriorated so as to impair safety:	<ul> <li>8.5 Low voltage (e.g. 230 volts) socket-outlets sited at least 3 m from Zone 1: ()</li> <li>8.6 Suitability of equipment for external influences for installed location in terms of IP rating: ()</li> <li>8.7 Suitability of equipment for installation in a particular zone: ()</li> </ul>
<ul> <li>5.15 Cables segregated / separated from non-electrical services: (N/A)</li> <li>5.16 Termination of cables at enclosures (extent of sampling indicated in PART 7 of the report):</li> <li>a) Connections coundly made and under no under no under the formation of the report):</li> </ul>	7.4       Suitability for the environment and external influences:       ()         7.5       Security of fixing:       ()         7.6       Cable entry holes in ceiling above luminaires, sized or sealed       ()	9. Other Part 7 special installations or locations List of all other special installations or locations, if any, present: N/A
b)       No basic insulation of a conductor visible outside enclosure       ()         c)       Connection of live conductors adequately enclosed       ()	so as to restrict the spread of fire: () List number and location of luminaires inspected on a separate page: Page No. (N/A)	······
d) Adequately connected at point of entry to enclosure       ()         5.17 Condition of accessories including socket-outlets, switches and joint boxes is satisfactory:       ()	7.7 Recessed luminaires (downlighters):       (N/A)         a) Correct type of lamps fitted       (N/A)         b) Installed to minimise build-up of heat       (N/A)	······· ()
6. Isolation and switching (isolation, switching off for mechanical maintenance and functional switching)	c)       No signs of overheating to surrounding building fabric       (N/A)         d)       No signs of overheating to conductors / terminations       (N/A)	Indicate if the relevant requirements of Part 7 are satisfied and append results of inspection on a separate numbered page.
<ul> <li>6.1 In general: <ul> <li>a) Presence and condition of appropriate devices</li> <li>b) Correct operation verified</li> <li>c) For isolation and switching for mechanical maintenance only: <ul> <li>a) Capable of being secured in the OFF position, where appropriate</li> <li>c)</li></ul></li></ul></li></ul>	8. Location(s) containing a bath or shower         8.1 Additional protection by RCD not exceeding 30 mA:         a) For low voltage circuits serving the location         b) For low voltage circuits passing through Zone 1 and Zone 2 not serving the location         (N/A)	SCHEDULE OF ITEMS INSPECTED BY JASON TODD Name (capitals): Signature:
PART 11 : SCHEDULES AND ADDITIONAL PAGES		
Schedule of Inspections         Schedule of Circuit Details an for the installation           Page No(s):         (4&5)         Page No(s):         (6, 7)	for additional sources (indicated in it	Continuation sheets       tem 9. above)       (None       (None       (None

The pages identified are an essential part of this report (see Regulation 653.2).

All fields must be completed. Enter either, as appropriate: '\screwt' if Acceptable condition; 'N/A

Certsure LLP operates the NICEIC & ELECSA brands

This report is based on the model forms shown in Appendix 6 of BS 7671

Warwick House, Houghton Hall Park, Houghton Regis, Dunstable, LU5 5ZX

Published by Certsure LLP

**'N/A'** if Not applicable; **'LIM'** if a L

: **'LIM'** if a Limitation exists:

or Code appropriately – CODE 'C1', 'C2', 'C3' or 'FI' (codes to be recorded in PART 6, with additional comments (where appropriate) on attached numbered sheets)



### This report is not valid if the serial number has been defaced or altered 25549646

#### DPN18C

## **DOMESTIC ELECTRICAL INSTALLATION CONDITION REPORT** Small installations up to 100 A single phase supply

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

CODE	S for Type of wiring (A) Thermoplastic insulated sheathed cables	<sup>d /</sup> (B)	Thermoplast metallic con	tic cables ir duit	1 (C) 1	hermoplast on-metallic	ic cables in conduit	(D) Thermop	olastic cable trunking	<sup>s in</sup> (E	) Thermopla	astic cables ir Ilic trunking	1 (F) The	ermoplastic /	SWA cables	(G) Thermo	osetting / SWA	cables (H	) Mineral-insu	lated cables	(O) other	- state:	N/A			
	Circuit description		ро		Cir	cuit ctor csa	uo	ľ	Protective			RCD	i permitted nstalled e device**	Circuit impedances (Ω)					Insu	lation resis	tance		earth ce, <i>Zs</i>	RCD operating		est tons
Circuit number	* Where this consumer unit is remote from the origin of the installation, record details of the circuit supplying this consumer unit on the first line.		Reference Metho ( <i>BS 7671</i> )	Number of points served	line		Max. disconnection time ( <i>BS 7671</i> )	BS (EN)	Type	Rating	Short-circuit capacity	Operating current, $I_{\Delta n}$	Maximum perr Zs for instal protective dev	(mea	g final circuits only easured end to end)		All circuits (complete at least one column)		Live / Live	Live / Earth	Test voltage DC	Polarity	Max. measured earth ault loop impedance, <i>Zs</i>	time	RCD	AF
			"	Nun	Live (mm <sup>2</sup> )	cpc (mm <sup>2</sup> )	≥ (s)			(A)	∽ (kA)	(mA)	(Ω)	(Line) r <sub>1</sub>	(Neutral) <i>r<sub>n</sub></i>	(cpc) <i>r</i> 2	$(R_1 + R_2)$	R <sub>2</sub>	(MΩ)	(MΩ)	(V)	(⁄)	 (Ω)	(ms)	(⁄)	(,
C	ooker	A	С	1	6	2.5	0.4	60898	В	32	6	30	1.37	N/A	N/A	N/A	0.32	N/A	50	50	500	V	0.38	28	~	N/A
_	ockets Landing	A	~		2.5	1.5	0.4	60898	_	32	-	30		0.48	0.48	0.80	0.55	N/A	50	50	500	~	0.62	28	~	N/A
S	ockets Kitchen and hall	A	-	6	2.5	1.5	0.4	60898	В	32	6	30		0.28	0.28	0.46	0.80	N/A		50	500	~	0.85	28	~	N/A
S	ockets	A	С	6	2.5	1.5	0.4	60898	В	16	6	30	2.73	0.45	0.45	0.75	0.57	N/A	50	50	500	V	0.64	28	~	N/A
E	oiler	A	С	1	2.5	1.5	0.4	60898	В	16	6	30	2.73	N/A	N/A	N/A	0.62	N/A	50	50	500	V	0.68	28	~	N/A
S	hower 1 landing	A	С	1	6	2.5	0.4	60898	В	40	6	30	1.09	N/A	N/A	N/A	0.20	N/A	50	50	500	~	0.24	28	~	N/A
L	ights bedrooms	A	С	5	1	1	0.4	60898	В	6	6	30	7.28	N/A	N/A	N/A	0.93	N/A	50	50	500	V	0.98	28	~	N/A
L	ights Downstairs hallway	A	С	5	1	1	0.4	60898	В	6	6	30	7.28	N/A	N/A	N/A	0.83	N/A	50	50	500	V	0.87	28	~	N/A
L	ights Upstairs hallway	A	С	4	1	1	0.4	60898	В	6	6	30	7.28	N/A	N/A	N/A	0.81	N/A	50	50	500	V	0.86	28	~	N/A
) S	ockets	A	С	1	2.5	1.5	0.4	60898	в	32	6	30	1.37	0.51	0.51	0.84	0.51	N/A	50	50	500	~	0.57	28	~	N/A
Loca	tion of consumer unit:Hallway								C	)esigna	ntion:	)B1									ault curr it <i>(where</i>			<u>:</u> (N/A	) kA	
	TED BY Name (capitals):JASO							Pos	ition:	S					Signat	ture:	$\geq$		<u> </u>			Dat		06/2022		
TES	T INSTRUMENTS (enter serial nu	umber a	against e	each ins	strumen	t used)																				
Mult N/A		Contin N/A	uity:				lns N/A	ulation res	istance	:		Earth N/A	n fault loo	op imped	lance:		Earth el N/A	ectrode	resistan	ce:		CD: I/A				

Original (to the person ordering the work)



**Original** (to the person ordering the work)

## **CONTINUATION SHEET:**

## **DOMESTIC ELECTRICAL INSTALLATION CERTIFICATE Small installations up to 100 A single phase supply &** DOMESTIC ELECTRICAL INSTALLATION CONDITION REPORT Small installations up to 100 A single phase supply Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

DC Dele	<b>N / DPN : SCHEDULE OF CIRC</b>	UIT D	ETAIL	S ANE	) TEST	RESU	ILTS	Circuits	/equipn	nent vu	Inerable	e to dam	age whe	n testing										•••••		
CO	DES for Type of wiring (A) Thermoplastic insulate sheathed cables	<sup>i/</sup> (B)	Thermoplas metallic cor	tic cables i nduit	n (C) <sub>n</sub>	hermoplasti on-metallic	c cables in conduit	(D) <sup>Thermop</sup> metallic t	lastic cable: runking	<sup>s in</sup> (E	) Thermopla non-metal	astic cables ir lic trunking	י <b>(F)</b> דוי	ermoplastic / S	SWA cables	(G) Thermos	setting / SWA	cables (H	) Mineral-insu	lated cables	(0) other	- state:	N/A			
Ъ	Circuit description	6	poq	served		cuit ctor csa	tion 1)	F	rotective	device			permitted nstalled e device**		Circu	it impedanc	es (Ω)		Insu	lation resist	ance	τţ.	l earth ince, Zs	RCD operating		Test ittons
Circuit number	* Where this consumer unit is remote from the origin of the installation, record details of the circuit supplying this consumer unit on the first line.	Type of wiring (see Codes)	Reference Method ( <i>BS 7671</i> )	Number of points served	Live (mm <sup>2</sup> )	cpc (mm <sup>2</sup> )	() Max. disconnection () time (BS 7671)	BS (EN)	Type	( <del>)</del> Rating	(文) Short-circuit (文) capacity	ii) Operating (V current, I <sub>∆n</sub>	ත Maximum pe වි Z <sub>S</sub> for inst protective de	(mea (Line)	final circuit sured end t (Neutral)	co end) (cpc)	(comple one c	ircuits te at least column)	Live / Live (MΩ)	Live / Earth (MΩ)	Test voltage DC (V)		(C) Max. measured earth (C) fault loop impedance, Zs	time (ms)	RCD (√)	AFD
	Shower	A	С	1	10	6	0.4	60898	В	(A) 40	(KA)	(IIIA) 30	1.09	r <sub>1</sub> N/A	r <sub>n</sub> N/A	r <sub>2</sub> N/A	$(R_1 + R_2)$ LIM	R <sub>2</sub> N/A	50	(IVIS2) 50	500	() ()	LIM	26		N/A
	4 bedroom sockets	A	C	4	2.5	- 1.5	0.4	60898	B	16	6				N/A		0.63	N/A	50		500	-	0.67	26	~	N/A
	1 socket in room above	A	С	3	2.5	1.5	0.4	60898	В	16	6				N/A		0.40		50		500	-	0.45	26	V	N/A
	Wifi socket	A	С	2	2.5	1.5	0.4	60898	В	16	6	30	2.73	N/A	N/A	N/A	0.25	N/A	50	50	500	~	0.31	26	~	N/A
	Emg Lighting	A	С	9	1	1	0.4	60898	В	6	6	30	7.28	N/A	N/A	N/A	0.96	N/A	50	50	500	~	1.01	26	~	N/A
	3no sockets and sini flow	A	С	4	2.5	2.5	0.4	60898	В	16	6	30	2.73	N/A	N/A	N/A	0.83	N/A	50	50	500	V	0.87	26	~	N/A
	Top room sockets 3	A	С	3	2.5	2.5	0.4	60898	В	16	6	30	2.73	N/A	N/A	N/A	0.82	N/A	50	50	500	V	0.87	26	~	N/A
_	4 bed room sockets	A	С	4	2.5	2.5	0.4	60898	В	16	6	30	2.73	N/A	N/A	N/A	0.86	N/A	50	50	500	V	0.91	26	V	N/A
	smoke alarms	A	С	9	1	1	0.4	60898	В	6	6	30	7.28	N/A	N/A	N/A	0.89	N/A	50	50	500	~	0.99	26	~	N/A
)	Lights	A	С	10	1	1	0.4	60898	В	6	6	30	7.28	N/A	N/A	N/A	1.06	N/A	50	50	500	~	1.13	26	~	N/A
																										+
	cation of consumer unit: .Entrance h	allway							D	lesigna	tion:	B2								pective fa umer uni				(2.6	) kA	4
	STED BY JASO Name (capitals):							Posi	Q ition:	S					Signa	ture:	$\geq$	7	2		••••••	Dat	30/ e:	06/2022		
	ST INSTRUMENTS (enter serial n			each in	strumen	t used)	1.					1									1 -					
		Contin	uity:					ulation resi	stance				n fault lo	op imped	ance:			lectrode	resistan	ce:		CD:				
10	11335898 N/A N											N/A					N/A				N,	Ά				

Published by Certsure LLP Certsure LLP operates the NICEIC & ELECSA brands Warwick House, Houghton Hall Park, Houghton Regis, Dunstable, LU5 5ZX

#### **NOTES FOR RECIPIENT** THIS CONDITION REPORT IS AN IMPORTANT AND VALUABLE DOCUMENT WHICH SHOULD BE RETAINED FOR FUTURE USE

The purpose of a domestic periodic inspection is to determine, so far as is reasonably practicable, whether the electrical installation of a single dwelling (house or flat) is in a satisfactory condition for continued service. This report provides an assessment of the condition of the electrical installation identified overleaf at the time it was inspected and tested, taking into account the stated extent of the installation and the limitations of the inspection and testing.

The report identifies any damage, deterioration, defects and/or conditions found by the inspector which may give rise to danger (see PART 6), together with any items for which improvement is recommended.

If you were the person ordering this report, but not the user of the installation, you should pass this report, or a full copy of it including these notes, the schedules and additional pages (if any), immediately to the user.

This report should be retained in a safe place and shown to any person inspecting or undertaking further work on the electrical installation in the future. If you later vacate the property, this report will provide the new user with an assessment of the condition of the electrical installation at the time the periodic inspection was carried out.

Where the installation incorporates a residual current device (RCD) there should be a notice at or near the device stating that it should be tested every six months. For safety reasons it is important that this instruction is followed.

For safety reasons, the electrical installation should be re-inspected at appropriate intervals by a skilled person or persons, competent in such work. The recommended date by which the next inspection should be carried out is stated in PART 5 of this report. There should also be a notice at or near the main switchboard or consumer unit indicating when the next inspection of the installation is due. NICEIC\* recommends that you engage the services of an NICEIC Approved Contractor for the inspection.

This report has been issued in accordance with the national standard for the safety of electrical installations, *BS* 7671: 2018 – *Requirements for Electrical Installations*.

Only an NICEIC Approved Contractor or Conforming Body is authorised to issue this NICEIC Domestic Electrical Installation Condition Report. You should have received the report marked 'Original' and the Approved Contractor should have retained the report marked 'Duplicate'.

This report form is intended to be issued only for the purpose of reporting on the condition of an existing electrical installation and must not be issued to certify new electrical installation work including the replacement of a consumer unit.

The report consists of at least six numbered pages. Additional numbered pages may have been provided to permit further relevant information relating to the installation to be recorded. For installations having more than one consumer unit or more circuits than can be recorded in PART 12, one or more additional *Schedules of Circuit Details and Test Results* should form part of the report. The report is invalid if any of the schedules identified in PART 10 are missing. The report has a printed serial number, which is traceable to the Contractor to which it was supplied.

PART 7 (Details and limitations) should identify fully the extent of the installation covered by this report and any limitations on the inspection and testing. The inspector should have agreed these aspects with the person ordering the report before the inspection was carried out.

Rarely, an operational limitation may have been encountered during the inspection such as inability to gain access to parts of the installation or to an item of equipment. The inspector should have noted any such limitations in PART 7. It should be noted that the greater the limitations applying to a report, the less its value from the safety aspect.

A declaration should have been given by the inspector in PART 4 of the report. The declaration must reflect the statement given in PART 3, which summarises the observations and recommendations made in PART 6. Where one or more observations have been made in PART 6, the Classification code given to each by the inspector indicates the degree of urgency with which remedial action needs to be taken to restore the installation to a safe working condition.

Where the inspector has indicated an observation as code C1 (danger present) **the safety of those using the installation is at risk**. Wherever practicable, items classified as (C1) should be made safe on discovery, and it is recommended that a skilled person(s) competent in electrical installation work undertakes the necessary remedial work immediately.

Where the inspector has indicated an observation as code C2 (potentially dangerous) **the safety of those using the installation may be at risk**, and it is recommended that a skilled person competent in electrical installation work undertakes the necessary remedial work as a matter of urgency.

Where the inspector has indicated that an item requires further investigation (FI), the investigation should be carried out without delay to determine whether danger or potential danger exists. For further guidance on the Classification codes, please see the reverse of page 2.

Where the installation can be supplied by more than one source, such as the public supply and a standby generator or microgenerator, this should be identified in PART 8 *Supply Characteristics and Earthing Arrangements*, and the *Schedules of Circuit Details and Test Results* (PART 12) compiled accordingly.

Where inadequacies in the intake equipment have been observed (Item 1 of PART 10), the person ordering the inspection should inform the distributor and/or supplier as appropriate.

Should the person ordering this report have reason to believe that it does not reasonably reflect the condition of the electrical installation reported on, that person should in the first instance raise the specific concerns in writing with the Approved Contractor. If the concerns remain unresolved, the person ordering this report may make a formal complaint to NICEIC, for which purpose a complaint form is available on request.

The complaints procedure offered by NICEIC is subject to certain terms and conditions, full details of which are available upon application. NICEIC does not investigate complaints relating to the operational performance of electrical installations (such as lighting levels), or to contractual or commercial issues (such as time or cost).

\* NICEIC is operated by Certsure LLP, a partnership between the Electrical Contractors' Association and the charity, Electrical Safety First. NICEIC maintains and publishes registers of electrical contractors that it has assessed against particular scheme requirements (including the technical standard of electrical work).

For further information about electrical safety and how NICEIC can help you, visit **www.niceic.com** 

## **GUIDANCE FOR RECIPIENTS ON THE CLASSIFICATION CODES**

Only one Classification code should be given for each recorded Observation

#### **Classification code C1 (Danger present)**

Where an observation has been given a Classification code C1, the safety of those using the installation is at risk and immediate remedial action is required.

The person ordering the inspection is advised to take action without delay to remedy the observed deficiency in the installation, or to take other appropriate action (such as switching off and isolating the affected part(s) of the installation) to remove the danger. The NICEIC Approved Contractor issuing this report will be able to provide further advice.

NICEIC makes available 'Electrical Danger Notification' forms to enable inspectors to record, and then to communicate to the person ordering the report, any dangerous condition discovered.

#### **Classification code C2 (Potentially dangerous)**

Classification code C2 indicates that, whilst those using the installation may not be at immediate risk, urgent remedial action is required to remove potential danger. The NICEIC Approved Contractor issuing this report will be able to provide further advice.

It is important to note that the recommendation given at PART 5 of this report (Next Inspection) for the maximum interval until the next inspection is conditional upon all items which have been given a Classification code C1 and code C2 being remedied immediately and as a matter of urgency, respectively.

It would not be reasonable for the inspector to indicate that the installation is in a satisfactory condition if any observation in this report has been given a code C1 or code C2 classification.

#### **Classification code C3 (Improvement recommended)**

Where an observation has been given a Classification code C3, the inspection and/or testing has revealed a non-compliance with the current safety standard which, whilst not presenting immediate or potential danger, would result in a significant safety improvement if remedied. Careful consideration should be given to the safety benefits of improving these aspects of the installation. The NICEIC Approved Contractor issuing this report will be able to provide further advice.

#### Code FI (Further investigation required without delay)

It should usually be possible for the inspector to attribute a Classification code to each observation without indicating a need for further investigation.

However, where 'FI' has been entered against an observation the inspector considers that further investigation of that observation is likely to reveal danger or potential danger that, due to the agreed extent or limitations of the inspection and/or testing, could not be fully identified at the time.

It would not be appropriate for the inspector to indicate that the installation is in a satisfactory condition if there is reasonable doubt as to whether danger or potential danger exists. Consequently, where the inspector has indicated 'Further investigation required without delay' (FI) the overall assessment of the installation (PART 3) should be marked as 'Unsatisfactory'.

If the inspector has indicated that an observation requires further investigation without delay, the person ordering this report is advised to arrange for the NICEIC Approved Contractor issuing the report (or another skilled person or persons competent in such work) to undertake further examination of that aspect of the installation as a matter of urgency, to determine whether or not danger or potential danger exists.

#### **Further information**

Further information on the application of Classification codes, primarily aimed at inspectors but of possible interest to persons ordering condition reports, can be found in Electrical Safety First's Best Practice Guide No 4 *Electrical installation condition reporting: Classification Codes for domestic and similar electrical installations.* The guide can be viewed or downloaded free of charge from www. electricalsafetyfirst.org.uk

For further information about electrical safety and how NICEIC can help you, visit www.niceic.com